## SECOND REGULAR SESSION

## House Concurrent Resolution No. 38

## 94TH GENERAL ASSEMBLY

5248L.01I

Whereas, traffic signals play a key role in intersection safety and minimize the potential of road user confusion at intersections; and

Whereas, in determining whether a traffic control signal is warranted at an 3 intersection, vehicular and pedestrian volumes, and crash history, including a record of severe 4 crashes, must be considered; and 5

Whereas, a comprehensive engineering study should be done to indicate whether 6 the installation of a traffic signal would improve the overall safety and operation of an 8 intersection; and

Whereas, recent requests of the Department of Transportation regarding the 9 possible placement of a traffic control signal at a busy intersection in Weldon Spring, Missouri, 10 have remained unresolved. To assure the safety of all drivers and pedestrians at and near the 11 intersection of Independence Road and State Highway 94 in Weldon Spring, Missouri, the 12 13 Department should immediately undertake a comprehensive engineering study of the intersection and respond to the repeated requests for improved traffic signaling at that intersection: 14

Now, therefore, be it resolved that the members of the House of 15 Representatives of the Ninety-fourth General Assembly, Second Regular Session, the Senate 16 concurring therein, hereby strongly urge the Department of Transportation to conduct a 17 comprehensive engineering study regarding the placement of a traffic control signal exhibiting 18 different colored lights at the intersection of Independence Road and State Highway 94 in the 19 City of Weldon Spring, St. Charles County, Missouri; and

20

Be it further resolved that the Chief Clerk of the Missouri House of 21 Representatives be instructed to prepare a properly inscribed copy of this resolution for Pete 22 Rahn, the Director of the Missouri Department of Transportation.